

## Speaker Type-K



*Full restoration of your Speaker Type-K pair - 2 pcs.*

**Your Speaker Type-K – Full restoration with the Classic Audio Certificate**

**9900 SEK**

Included in price:

- Full restoration of the product – mechanical – electrical and cosmetically
- Filter parts replaced and all speaker cones are specially coated.
- Cable and plugs replaced with high quality parts
- All speaker units are individually tested and matched for optimal sound distribution.
- Normal products repair
- Classic Audio test Certifikat for Speaker Type-K
- Classic Audio documents for Speaker Type-K - quality scanning of the original B&O user manual

This price does not include:

- Major product cabinet / veneer fault
- Replacement of
  - Cabinet parts
  - Replacement of drivers / speakers
  - Missing parts
- Swedish VAT
- Shipping cost

### Remarks:

Classic Audio will be working on Speaker Type-K at least 12 hours and test time is more than 2 hours followed by a quality assurance test period of 10 hours before delivery.

**Classic Audio can replace any parts of your Beovox 5000 you requests**

Major cabinet / veneer damages  
Frontcover major repair / replacement

### Driver units - speakers (price per. unit)

Replacement of one treble driver

Replacement of one 10" bass driver

Replacement of one midrange driver

300 SEK

1500 SEK

900 SEK

**After inspection of your product you will receive a complete cost quotation for the full restoration**

**all prices are excl. swedish VAT**

### Delivery conditions

Delivery time: 2 month

ExWorks – Classic Audio Venø (Shipping cost not included)

(On request Classic Audio arrange shipping of your product)

### Classic Audio Svenska AB

Dick Andersson

Falleniusgatan 4

703 41 Örebro

Sverige

### Payment conditions

Deposit at the time of delivery: 30% of the total invoice value.

The balance at the time of delivery – before shipping.

Tlf.: +46 764096158

CVR SE559483325201

Classic Audio reserves the right to refrain from restoring your Speaker Type-K if your product is in a poor condition which means the Speaker Type-K cannot be restored to obtain the classification a classic audio product